FITNESS CERTIFICATE TO BE FILLED BY THE INSPECTING OFFICER

(Assistant Engineer / Assistant executive Engineer)

1 Name of school

SREE GOKULAM PUBLIC SCHOOL, ATTINGAL

2 Name of Officer

: Smt REMYA NC

3 Location

: KIZHUVILAM/ ATTINGAL DEO

4 Period for which the certificate is issued

· 2025-26

1)BLOCK A - Conducting classess in the class rooms adjoining the bay area across all floors prohibited due to structural failure seen near expansion joint

61.00*10.10*3.60m(4 floors)

11.50*9.50*3.60m(3 floors)

Admin room,Offoce Room, Guest Room,Store room,Principal Room, Exam Cell,EngNsh Department,X-1no,XII-2no,IX-1 no,XI-2 nos,Meeting Hall,Science Department,Maths Department,Malayalam Department,IP Department,Hindi Department,SS Department,Faculty Room,IX -SMART CLASS ROOM

2)BLOCK B-

53.50*21.10*3.60M(4 Floors)

Mess ,PRE KG,LKG-2nos, UKG-2 nos.KG Department,IN DOOR ,Smart Class Room For XI,XII,Auditorium

3)BLOCK C

29.00*8.70*3.00m (3 floors)

55.45*9.80*3.00m(3 floors)

5 Type of Ruiding

Selt offested

Soll Pillerich

QUIZ Club,VIII-2 nos,VII-1no,VI-1no,I-2nos, II-2nos,III-1no,IV-1no,Hindi Department,Hindi Room, Panel Room(VIII),Nursing Room,Physical lab,Biology Lab,Chemistry Lab,PE Department,Panel Room(VII)English lab,IT lab,Malayalam Department,IT lab.Malayalam Club,Pannel(VI),Pannel(V),X-1no,IX-1no,Hindi Club,Yoga Room,Music Room,Staff Room

4)BLOCK D

29.00*8.00*3.00m(3 floors)

6.80*5.00*3.00m(3 floors)

DANCE.MUSIC,ART/CRAFT STORE ROOM,YOGA 1,YOGA2,ART/CRAFT ROOM,PSY LAB,Special aid department,GEO LAB, MATHS LAB, LIBRARY, INDOOR GAME

4)BLOCK E

19.50*8.00*3.10m(3 floors)

13.00*8.15*3.10m(3 floors)

Store Room- Work Shop-2 nos, Godown-4 nos, Stitching Room, Tailors Room

6 Nature of Defect if any:

a) Foundation and basement

Superstructure

c) Doors and windows

d) Wood work wrought and put up

e) Flooring

f) Miscellaneous

7 Any major defects noticed which will render the building unsafe in any manner

8 Whether maintenance work have been done properly

Nil

Nil

YES

Selt attested

8 all Altested

Whether the structure is sound or not for Conduting classes

It is safe to conduct the classes under normal weather conditions

The stability of the structure should be examined also with reference to location altitude intensity of wind exposure of flood etc.

2. Any additional observation deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 16.06.2025 and found to be fit to conduct casses for the period for the reasons stated above.

Place: Kizhuvilam

Signature:

Date: 26.06.2025

Designation:

138mm No: 9.

Assistant Engineer

Kizhuvilam Grama Panchayath

Self affected

3 all Altertad