FITNESS CERTIFICATE TO BE FILLED BY THE INSPECTING OFFICER

(Assistant Engineer / Assistant executive Engineer)

| 1 | Name of school | | | Sree Gokulam Public school, Atting | |
|-------|--|-----------------------|-----------------------------|------------------------------------|---|
| 2 | Name of Officer | | : | Smt Remya N C | |
| 3 | Location | | | : | Attingal DEO |
| 4 | Period fo | r which the certifica | ate is issued | : | 2023-24 |
| 5 | Type of E | Buiding | | \$ | RCC Building -A-61*10.10*3.60 (4 Floors) , 11.50*9050*3.60(3 floors), B-53.50*21.10+3.60(4 floors) |
| | | | | | 55.45*9.80*3.00(3 floors) |
| | | | | | D-29.00*8.00*3.00(3 floors) 6.80*5.00*3.00(3 floors) |
| | | | | | E-19.50*8.00*3.10(3 floors) |
| 6 | Nature of | f Defect if any: | | | |
| | a) | Foundation and ba | asement | : | 7 |
| | b) | S | uperstructure | : | |
| | c) | D | oors and windows | * | Nil |
| | d) | | lood work wrought and ut up | : | |
| | e) | F | looring | | |
| | f) | M | liscellaneous | : | |
| 7 | Any major defects noticed which will render the | | | | _' |
| | | | | : | Nil |
| | building | unsafe in any man | ner | | |
| 8 | Whether maintenance work have been done | | 1 | YES | |
| | properly | | | | |
| 9 | Whether the structure is sound or not for Conduting classes | | | ; | It is safe to conduct the classes under normal weather conditions |
| Note: | The stability of the structure should be examined also with reference to location altitude intensity of wind exposure of flood etc | | | | |
| | 2, Any additional observation deemed necessary for the certificate may be furnished separately with the certificate. | | | | |
| | | | | | |

Certified that the school was inspected by me on 14/6/2023and found to be fit to conduct classes for the period of 2023-24 for the reasons stated above.

Grama Panchaya

Place:

Kizhuvilam

Signature:

Designation:

Assistant Engineer Local Self Govt. Dept Kizhuvilam Grama Panchayath