

**FITNESS CERTIFICATE**  
**TO BE FILLED BY THE INSPECTING OFFICER**  
(Assistant Engineer / Assistant executive Engineer)

- 1 Name of school : SREE GOKULAM PUBLIC SCHOOL, ATTINGAL
- 2 Name of Officer : Smt REMYA NC
- 3 Location : ATTINGAL DEO
- 4 Period for which the certificate is issued : 2024-25
- 1) **BLOCK A** - Conducting classes in the class rooms adjoining the bay area across all floors prohibited due to structural failure seen near expansion joint
- 61.00x10.10x3.60m (4 floors)  
11.50x9.50x3.60m (3 floors)
- Admin Room, Office, Guest Room, Store Room, Principal Room, Exam Cell, English Department, X-1 no, XII-2 nos, IX-1 no, XI-2 NOS, Meeting Hall, Sci Department, Maths Department, Malayalam Department, IP DEPT, Hindi Department, SS Department, Faculty Room, IX- SMART CLASS ROOM
- 2) **BLOCK B**
- 53.50x21.10x3.60m (4 floors)
- Mess, PRE KG, LKG-2 nos, UKG-2 nos, KG Department, IN DOOR, Smart Class Room For XI, XII, Auditorium
- 3) **BLOCK C**
- QUIZ Club, VIII- 2 nos, VII-1 no, VI-1 no, I-2 nos, II-2 nos, III-1 no, IV-1 no, Hindi Department, Hindi Room, Panel Room (VIII), Nursing Room, Physics Lab, Biology Lab, Chemistry Lab, PE Department, Panel Room (VII) English Lab, IT Lab, Malayalam Department, IT Lab, Malayalam Club, Pannel (VI), Pannel (V), X-1 no, IX-1 no, Hindi Club, Yoga Room, Music Room, Staff Room
- 29.00x8.70x3.00m (3 floors)  
55.45x9.80x3.00m (3 floors)
- 4) **BLOCK D**

Self collected  
[Signature]

- Self Assessed -  
[Signature]

DANCE,MUSIC,ART/CRAFT STORE  
ROOM, YOGA1,YOGA 2,ART/CRAFT  
ROOM,PSY LAB,Specialdepartment,GEO  
LAB,MATHS LAB,LIBRARY, INDOOR  
GAME

29.00X8.00X3.00m(3 floors)

6.80X5.00X3.00m(3 floors)

5)BLOCK E

Storeroom-Work Shop- 2nos,Godown-4nos.  
Stitching Room,TailorsRoom

19.50x8.00x3.10m(3 floors)

13.00x8.15x3.10m(3 floors)

6 Nature of Defect if any :

a) Foundation and basement

b) Superstructure

c) Doors and windows

d) Wood work wrought and put up

e) Flooring

f) Miscellaneous

Nil

7 Any major defects noticed which will render the

Nil

8 Whether maintenance work have been done

YES

9 Whether the structure is sound or not for  
Conducting classes

It is safe to conduct the classes  
under normal weather conditions

Note: 1, The stability of the structure should be examined also with reference to location  
2, Any additional observation deemed necessary for the certificate may be furnished

Certified that the school was inspected by me on 27.06.2024

Place: Kizhuvilam

Date: 27.06.2024

and found to be fit to

Signature:  
Designation:

Issued no 17



Assistant Engineer  
Local Self Govt. Dept  
Kizhuvilam Grama Panchayath